

Car Credit Nation

WE DELIVER MORE THAN JUST CARS

2014 LINCOLN MKS

Stock #: 22590R

Transmission: AUTOMATIC

VIN #: 1LNHL9DKXEG602554

ENGINE: 3.7 L, V6

INTERIOR: LIGHT DUNE PREMIUM LEATHER

DRIVE TRAIN: Front-wheel drive

COLOR: White

MILEAGE: 92704



**VEHICLE
HISTORY
REPORT**

Tier 3

Scan for Pricing and
Payment Details



Fuel Economy

CITY HWY
19 28

SALES HOURS

Mon-Fri 9am-6pm

Sat- 9am-5pm

Dealer Contact Info

Phone - 540 323-7555

Sales@carcreditnation.com

- » Front mounted engine
- » Regular Unleaded
- » Spark ignition system
- » Transverse mounted engine
- » Aluminum engine block
- » Aluminum cylinder head
- » Alternator
- » Lead acid battery
- » Battery run down protection
- » Radiator
- » AdvanceTrac electronic stability control system
- » 4-wheel disc brakes
- » 4-wheel antilock (ABS) brakes
- » Brake assist system
- » Projector beam headlights
- » High-intensity discharge low and high beam headlights
- » Auto on/off headlight control
- » Daytime running lights
- » Delay-off headlights
- » Directionally adaptive headlights
- » ULEV II emissions
- » Tier 2 Bin 5 emissions
- » Composite/galvanized steel body panels with side impact beams
- » 4 doors
- » Body-colored front bumper
- » Body-colored rear bumper
- » Stainless steel bodyside insert
- » Chrome grille
- » Stainless steel side window trim
- » Chrome door handles
- » Tri-coat paint
- » Monotone paint
- » Conventional left rear passenger door
- » Power door mirrors
- » Trunk
- » Heated driver and passenger side door mirrors
- » Conventional right rear passenger door
- » Driver visor mirror
- » Illuminated driver visor mirror
- » Passenger visor mirror
- » Illuminated passenger visor mirror
- » Auto-dimming rear view mirror
- » 5
- » Bucket front seats
- » Heated driver and front passenger seats
- » Ventilated driver and front passenger seats
- » Driver seat with 8-way directional controls
- » Front passenger seat with 8-way directional controls
- » Massaging lumbar front passenger seat
- » Height adjustable front seat head restraints
- » Manual front seat head restraint control
- » Driver seat armrest
- » Seek scan
- » Single-disc CD player
- » CD player located in the dashboard/instrument panel
- » THX II radio
- » Radio data system (RDS)
- » CD player MP3 decoder
- » Auxiliary input jack
- » SYNC with MyLincoln Touch external memory control
- » Performance grade speakers
- » 600W amplifier
- » Integrated navigation system with voice activation
- » Bluetooth handsfree wireless device connectivity
- » Selective service internet access

Price Disclaimer - The total sales price is **\$13990.00**. The displayed price is the total sales price not including a **\$495** doc fee, state and local tax, registration fees, interest, or optional products such as GAP insurance or a vehicle service contract. Please see dealer for personalized financing terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

BUYERS GUIDE-

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

LINCOLN MKS 2014 1LNHL9DKXEG602554
VEHICLE MAKE MODEL YEAR VEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:

AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

DEALER WARRANTY

- FULL WARRANTY.
- LIMITED WARRANTY. The dealer will pay 100 % of the labor and 100 % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

DURATION:

NON-DEALER WARRANTIES FOR THIS VEHICLE:

- MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
- MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
- OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.

- SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's law may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

Engine

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

- Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

Brake System

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

Steering System

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

Suspension System

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- Leakage
- Catalytic Converters

Airbags

CAR CREDIT NATION

DEALER

1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602

ADDRESS

Jacob Maher(540-323-7555)

Email: Jacob@carcreditnation.com

SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

CUSTOMERS SIGNATURE

DATE

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)