Car Credit Nation

WE DELIVER MORE THAN JUST CARS

2011 NISSAN SENTRA

Stock #: 20471

Transmission: Continuously Variable Transmission

VIN #: 3N1AB6AP0BL713406

ENGINE: 2.0L/122L

INTERIOR:

DRIVE TRAIN: Front Wheel Drive

COLOR: Brilliant Silver Metallic

MILEAGE: 144672



Tier 2

PRICE:* \$8,490

Financing As Low As:

\$65 / week \$495 / down



SALES HOURS Mon-Fri 9am-6pm Sat- 9am-5pm

Dealer Contact Info

Phone - 540 323-7555 Sales@carcreditnation.com

- » 2.0L DOHC 16-valve SMPI I4 engine
- » Electronically controlled drive-by-wire throttle
- » Xtronic continuously variable transmission (CVT)
- » Front wheel drive
- » Battery saver
- » Independent strut front suspension
- » Rear torsion beam suspension
- » Front/rear stabilizer bars
- » Electric pwr rack & pinion steering
- » Pwr front ventilated disc/rear drum brakes
- » 16" steel wheels w/full wheel covers
- » P205/55HR16 all-season tires
- » Compact spare tire
- » Body color bumpers
- » Body-side moldings w/chrome insert
- » Chrome trunk lid finisher
- » Body-colored rear decklid spoiler
- » Multi-reflector halogen headlamps -inc: auto off headlamp feature in battery saver
- » Body color pwr mirrors
- » Green tinted glass
- » Variable intermittent windshield wipers
- » Body-color door handles
- » Fixed roof antenna
- » Suede cloth seat trim
- » Front bucket seats -inc: 6-way manual adjustable driver w/height adjustment, 4-way manual adjustable passenger
- » 60/40 split fold-flat rear seats -inc: height adjusters on outboard seating positions
- » Front center console w/armrest, dual cup holders, console light
- » 1 DIN size utility box w/lid
- » Floor & trunk carpeting
- » Instrument panel utility storage bin
- » Tilt steering column
- » Steering wheel mounted illuminated cruise & audio controls
- » Trip computer
- » Instrumentation -inc: outside temp gauge, fuel consumption gauge, tachometer
- » Vehicle security system

- » Pwr windows w/driver 1-touch auto up/down, auto reverse
- » Air conditioning w/in-cabin micro filter
- » Rear window defroster w/timer
- » Suede cloth door trim
- » Oversize glove box
- » (2) 12V pwr outlets
- » Rear center armrest w/(2) cup holders
- » Rear parcel shelf
- » Cargo area light
- » Daytime illumination
- » Overhead map light
- » Front passenger seatback map pocket
- » Driver/front passenger door map pockets
- » Dual covered visor vanity mirrors
- » Chrome plated interior door handles
- » Front/rear passenger assist grips
- » Trunk lid inside trim
- » Anti-lock braking system w/electronic brake force distribution
- » Side-door guard beams
- » Zone body construction w/front/rear crumple zones, hood deformation point
- » Dual-stage driver/front passenger airbags w/occupant classification sensor
- » Driver/front passenger side-impact airbags
- » Roof mounted curtain air bags for outboard positions
- » Front seatbelt pretensioners w/adjustable upper anchorages & load limiters
- » 3-point ELR driver seat belt
- » 3-point ALR/ELR seat belts for passenger seating positions
- » Child safety rear door locks
- » Passenger window lockout
- » Child seat anchorages in rear outboard seating positions (LATCH)
- » Emergency inside trunk release
- » Active adjustable front head restraints
- » Energy absorbing steering column
- » Tire pressure monitoring system

Price and Payment Disclaimer - The total sales price is \$8490.00. The displayed **amount financed** is the remainder of the sales price after a \$495 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 143 weekly payments and an interest rate of 9.9% per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

NISSAN SENTRA 2011 3N1AB6AP0BL713406

VEHICLE MAKE MODEL YEAR VEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:

AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

DEALER WARRANTY

FULL WARRANTY.

LIMITED WARRANTY. The dealer will pay **_100**_ % of the labor and **_100**_ % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3.000 MILES. WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

NON-DEALER WARRANTIES FOR THIS VEHICLE:

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
OTHER USED VEHICLE WARRANTY APPLIES.
Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.
SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage,

deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied* warranties under your state's law may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain avehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- · Heater & Deforester

Brake System

- Failure warning light broken
 Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering SystemToo much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jamsFront wheels aligned improperly (DOT
- Power unit belts cracked or slippingPower unit fluid level improper

Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected

- Spring broken
 Shock absorber mounting loose
 Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- LeakageCatalytic Converters

Airbags

CAR CREDIT NATION DEALER 1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602 **ADDRESS** Chris Maher Jr(540-323-7555) Email: ChrisJr@carcreditnation.com SEE FOR COMPLAINTS I hereby acknowledge notice of the Buyers Guide at the closing of this sale. **CUSTOMERS SIGNATURE** DATE