# **Car Credit Nation**

WE DELIVER MORE THAN JUST CARS

### **2017 FORD TAURUS**

Stock #: 20665

Transmission: 6-Speed Automatic

VIN #: 1FAHP2D84HG111170

ENGINE: 3.5 L/213L

INTERIOR: Dune

DRIVE TRAIN: Front Wheel Drive

COLOR: Ingot Silver Metallic

MILEAGE: 83075



## Tier 4

PRICE:\* \$15,990

Financing As Low As:

\$85 / week \$1.495 / down



**SALES HOURS** Mon-Fri 9am-6pm Sat- 9am-5pm

**Dealer Contact Info** Phone - 540 323-7555

Sales@carcreditnation.com

» Engine: 3.5L Ti-VCT V6 (FFV) -inc: Flexible Fuel Vehicle (FFV) system is standard equipment for vehicles w/the 3.5L Ti-VCT V6 engine shipped to Federal Emissions States or Cross Border State dealers and is only available w/a Federal emissions system, (FFV system not available w/code 422 and requires code 936 or 423 if applicable for California Emissions State dealer destinations), Cross border states include AZ, DC, ID, NH, NV, OH, VA, WV Not Standard Equipment in CA **Emissions States.** 

- » Front-Wheel Drive
- » 2.77 Axle Ratio
- » 72-Amp/Hr 650CCA Maintenance-Free Battery w/Run Down Protection
- » Gas-Pressurized Shock Absorbers
- » Front And Rear Anti-Roll Bars
- » Electric Power-Assist Speed-Sensing Steering
- » 19 Gal. Fuel Tank
- » Quasi-Dual Stainless Steel Exhaust w/Chrome » Rear Cupholder Tailpipe Finisher
- » Strut Front Suspension w/Coil Springs
- » Multi-Link Rear Suspension w/Coil Springs
- » 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs and Brake Assist
- » Brake Actuated Limited Slip Differential
- » Wheels: 18" Painted Aluminum » Tires: P235/55R18 A/S BSW
- » Aluminum Spare Wheel
- » Compact Spare Tire Mounted Inside Under
- » Clearcoat Paint
- » Body-Colored Front Bumper
- » Body-Colored Rear Bumper w/Black Rub Strip/Fascia Accent
- » Chrome Side Windows Trim and Black Front Windshield Trim
- » Body-Colored Door Handles
- » Black Power Side Mirrors w/Convex Spotter and Manual Folding
- » Fixed Rear Window w/Defroster
- » Light Tinted Glass

- » Speed Sensitive Variable Intermittent Wipers
- » Front Windshield -inc: Sun Visor Strip
- » Fully Galvanized Steel Panels
- » Chrome Grille
- » Trunk Rear Cargo Access
- » Auto On/Off Projector Beam Halogen Headlamps w/Delay-Off
- » Perimeter/Approach Lights
- » LED Brakelights
- » Laminated Glass
- » Window Grid Antenna
- » 2 LCD Monitors In The Front
- » Driver Seat
- » 2-Way Passenger Seat -inc: Manual Lumbar Support
- » 60-40 Folding Bench Front Facing Fold Forward Seatback Rear Seat
- » Manual Tilt/Telescoping Steering Column
- » Selective Service Internet Access
- » Front Cupholder
- » Keypad
- » Remote Releases -Inc: Power Cargo Access
- » Cruise Control w/Steering Wheel Controls
- » Manual Air Conditioning
- » HVAC -inc: Underseat Ducts and Console
- » Illuminated Locking Glove Box
- » Driver Foot Rest
- » Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert and **Chrome Interior Accents**
- » Full Cloth Headliner
- » Cloth Door Trim Insert
- » Urethane Gear Shifter Material
- » Day-Night Rearview Mirror
- » Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- » Full Floor Console w/Covered Storage, Mini Overhead Console w/Storage and 3 12V DC **Power Outlets**
- » Front And Rear Map Lights
- » Fade-To-Off Interior Lighting
- » Carpet Floor Trim and Carpet Trunk Lid/Rear Cargo Door Trim

**Price and Payment Disclaimer** - The total sales price is \$15990.00. The displayed **amount financed** is the remainder of the sales price after a \$1495 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 230 weekly payments and an interest rate of 9.9% per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

**Vehicle Details** - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

- » Cargo Space Lights
- » FOB Controls -inc: Cargo Access
- » Driver / Passenger And Rear Door Bins
- » Delayed Accessory Power
- » Driver Information Center
- » Analog Appearance
- » Seats w/Cloth Back Material
- » Manual w/Tilt Front Head Restraints and

Fixed Rear Head Restraints

- » Front Center Armrest and Rear Center Armrest
- » 2 Seatback Storage Pockets
- » Securilock Anti-Theft Ignition (pats)

#### Immobilizer

- » 3 12V DC Power Outlets
- » Air Filtration
- » Side Impact Beams
- » Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- » Low Tire Pressure Warning
- » Dual Stage Driver And Passenger Front Airbags
- » Safety Canopy System Curtain 1st And 2nd Row Airbags
- » Airbag Occupancy Sensor
- » Driver And Passenger Knee Airbag
- » Mykey System -inc: Top Speed Limiter, Audio Volume Limiter, Early Low Fuel Warning, Programmable Sound Chimes and

Beltminder w/Audio Mute

- » Rear Child Safety Locks
   » Outboard Front Lap And Shoulder Safety
   Belts -inc: Rear Center 3 Point, Height
   Adjusters and Pretensioners
- » Back-Up Camera
- » ENGINE: 3.5L TI-VCT V6 (FFV) -inc: Flexible Fuel Vehicle (FFV) system is standard equipment for vehicles w/the 3.5L Ti-VCT V6 engine shipped to Federal Emissions States or Cross Border State dealers and is only available w/a Federal emissions system, (FFV system not available w/code 422 and requires code 936 or 423 if applicable for California Emissions State dealer destinations), Cross border states include AZ, DC, ID, NH, NV, OH, VA, WV
- » INGOT SILVER METALLIC
- » DUNE, CLOTH BUCKET SEATS -inc: 6-way power driver and passenger seat (fore/aft, up/down, tilt) w/manual lumbar and recline

## **BUYERS GUIDE**

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

FORDTAURUS20171FAHP2D84HG111170VEHICLE MAKEMODELYEARVEHICLE IDENTIFICATION NUMBER(VIN)

#### **WARRANTIES FOR THIS VEHICLE:**

$\bigcup$	AS	IS-	NO	DEA	LER	WAF	RRA	NTY
	THE DEALE	R DOES N	NOT PROVID	E A WARRANT	FOR ANY R	<b>EPAIRS AFTE</b>	R SALE	

# DEALER WARRANTY

FULL WARRANTY.

 $\checkmark$ 

LIMITED WARRANTY. The dealer will pay **100** % of the labor and **100** % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

#### **SYSTEMS COVERED:**

INTERNALLY LUBRICATED PARTS (ONLY)

**ENGINE** 

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

#### **DURATION:**

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

#### NON-DEALER WARRANTIES FOR THIS VEHICLE:

	MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
	MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
	OTHER USED VEHICLE WARRANTY APPLIES.
As	sk the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.
<b>✓</b>	SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, <i>implied</i> warranties under your state's law may give you additional rights.

#### ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

**OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS.** For information on how to obtain avehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

#### Below is a list of some major defects that may occur in motor vehicles.

#### Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

#### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

#### **Differential**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

#### **Cooling System**

- Leakage including radiator
- Improperly functioning water pump

#### **Electrical System**

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

## **Fuel System**

Visible leakage

#### **Inoperable Accessories**

- Gauges or warning devices
- Air conditioner
- · Heater & Deforester

#### **Brake System**

- Failure warning light broken
  Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering SystemToo much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jamsFront wheels aligned improperly (DOT
- Power unit belts cracked or slippingPower unit fluid level improper

#### Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected

- Spring broken
  Shock absorber mounting loose
  Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

#### Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

#### Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

#### **Exhaust System**

- LeakageCatalytic Converters

#### Airbags

## CAR CREDIT NATION DEALER 1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602 **ADDRESS** Chris Maher Jr(540-323-7555) Email: ChrisJr@carcreditnation.com SEE FOR COMPLAINTS I hereby acknowledge notice of the Buyers Guide at the closing of this sale. **CUSTOMERS SIGNATURE** DATE