
Car Credit Nation WE DELIVER MORE THAN JUST CARS

2017 FORD FUSION

Stock #:	20687	Transmission:	6-Speed Automatic
VIN #:	3FA6P0H74HR102586	ENGINE:	2.5 L/152L
INTERIOR:		DRIVE TRAIN:	Front Wheel Drive
COLOR:	Ruby Red Metallic Tinted Clearcoat	MILEAGE:	76810



Financing As Low As: \$85 / week \$995 / down



SALES HOURS Mon-Fri 9am-6pm Sat- 9am-5pm

Dealer Contact Info Phone - 540 323-7555 Sales@carcreditnation.com

- » Engine: 2.5L iVCT » 50-State Emissions System
 - » Front-Wheel Drive
 - » 3.07 Axle Ratio
 - » 500CCA Maintenance-Free Battery w/Run
 - Down Protection
 - » Gas-Pressurized Shock Absorbers
 - » Front And Rear Anti-Roll Bars
 - » Electric Power-Assist Speed-Sensing Steering
 - » 16.5 Gal. Fuel Tank » Single Stainless Steel Exhaust w/Chrome
 - **Tailpipe Finisher**
 - » Strut Front Suspension w/Coil Springs
 - » Multi-Link Rear Suspension w/Coil Springs » 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs, Brake Assist, Hill Hold Control and Electric Parking Brake
 - » Brake Actuated Limited Slip Differential
 - » 17" X 7.5" Wheels
 - » Steel Spare Wheel
 - » Compact Spare Tire Mounted Inside Under Cargo
 - » Clearcoat Paint
 - » Body-Colored Front Bumper
 - » Body-Colored Rear Bumper
 - » Chrome Side Windows Trim
 - » Body-Colored Door Handles
 - » Body-Colored Power Side Mirrors w/Convex
 - Spotter and Manual Folding
 - » Fixed Rear Window w/Defroster
 - » Light Tinted Glass
 - » Fully Galvanized Steel Panels
 - » Chrome Grille
 - » Trunk Rear Cargo Access
 - » Perimeter/Approach Lights
 - » LED Brakelights
 - » Radio w/Seek-Scan, Clock, Speed
 - Compensated Volume Control, Steering Wheel Controls and Radio Data System
 - » Streaming Audio
 - » Integrated Roof Antenna
 - » 2 LCD Monitors In The Front
 - » Driver Seat
 - » Passenger Seat

- » 60-40 Folding Bench Front Facing Fold Forward Seatback Cloth Rear Seat
- » Manual Tilt/Telescoping Steering Column » SYNC Services Selective Service Internet
- Access
- » Front Cupholder
- » Rear Cupholder
- » Compass
- » Power Fuel Flap Locking Type
- » Remote Releases -Inc: Power Cargo Access
- » Keypad
- » Cruise Control w/Steering Wheel Controls
- » HVAC -inc: Underseat Ducts and Console
- Ducts
- » Illuminated Locking Glove Box
- » Driver Foot Rest

» Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert, Piano Black/Metal-Look Console Insert and **Chrome Interior Accents**

- » Full Cloth Headliner
- » Cloth Door Trim Insert
- » Metal-Look Gear Shifter Material
- » Day-Night Rearview Mirror
- » Driver And Passenger Visor Vanity Mirrors
- w/Driver And Passenger Illumination

» Full Floor Console w/Covered Storage. Mini Overhead Console w/Storage and 3 12V DC Power Outlets

- » Front And Rear Map Lights
- » Fade-To-Off Interior Lighting
- » Carpet Floor Trim and Carpet Trunk Lid/Rear
- Cargo Door Trim
- » Cargo Space Lights
- » Instrument Panel Bin, Driver / Passenger And Rear Door Bins
- » Delayed Accessory Power
- » Driver Information Center
- » Redundant Digital Speedometer
- » Outside Temp Gauge
- » Digital/Analog Appearance
- » Seats w/Cloth Back Material
- » Manual Adjustable Rear Head Restraints
- » 2 Seatback Storage Pockets

Price and Payment Disclaimer - The total sales price is \$15990.00. The displayed **amount financed** is the remainder of the sales price after a \$995 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 239 weekly payments and an interest rate of 9.9% per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

- » Front Center Armrest and Rear Center
- Armrest
- » Perimeter Alarm
- » Securilock Anti-Theft Ignition (pats)
- Immobilizer
- » 3 12V DC Power Outlets
- » Air Filtration

» Side Impact Beams

- » Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- » Tire Specific Low Tire Pressure Warning
- » Dual Stage Driver And Passenger Front
- Airbags
- » Curtain 1st And 2nd Row Airbags
- » Airbag Occupancy Sensor
- » Driver And Passenger Knee Airbag
- » Mykey System -inc: Top Speed Limiter,
- Audio Volume Limiter, Early Low Fuel Warning, Programmable Sound Chimes and
- Beltminder w/Audio Mute
- » Rear Child Safety Locks
- » Outboard Front Lap And Shoulder Safety
- Belts -inc: Rear Center 3 Point, Height
- Adjusters and Pretensioners
- » Back-Up Camera

BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

FORD VEHICLE MAKE FUSION MODEL <u>2017</u> YEAR 3FA6P0H74HR102586 VEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:

) AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

 \checkmark

DEALER WARRANTY

FULL WARRANTY.

LIMITED WARRANTY. The dealer will pay **_100**_ % of the labor and **_100**_ % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST 30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST 30 DAYS OR 3,000 MILES. WHICHEVER COMES FIRST

30 DATS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST 30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

ANES AN ANES

NON-DEALER WARRANTIES FOR THIS VEHICLE:

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.

MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.

OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.

SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's law may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtaina vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

Engine

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by
- faulty transmission or drive shaft • Improper shifting or functioning of any
- gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

Brake System

- Failure warning light broken
 Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering System Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
 Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
 Power unit fluid level improper

Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected

- Spring broken
 Shock absorber mounting loose
 Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- LeakageCatalytic Converters

Airbags

CAR CREDIT NATION

DEALER

1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602

ADDRESS

Chris Maher Jr(540-323-7555) ------

Email: ChrisJr@carcreditnation.com

SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

CUSTOMERS SIGNATURE

DATE

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)
