Car Credit Nation

WE DELIVER MORE THAN JUST CARS

2015 HYUNDAI SONATA

Stock #: 20672

Transmission: 7-Speed Automatic

VIN #: 5NPE24AF1FH002832

ENGINE: 2.4 L/144L

INTERIOR:

DRIVE TRAIN: Front Wheel Drive

COLOR: Quartz White Pearl

MILEAGE: 109369



Tier 3

PRICE:* \$12,990

Financing As Low As: \$78 / week

\$495 / down



SALES HOURS Mon-Fri 9am-6pm Sat- 9am-5pm

Dealer Contact Info Phone - 540 323-7555

Sales@carcreditnation.com

- » Engine: 2.4L GDI 4-Cylinder
- » Transmission: 6-Speed Automatic w/SHIFTRONIC -inc: OD lock-up torque converter, shift lock and SHIFTRONIC manual shift mode
- » Transmission w/Driver Selectable Mode and Oil Cooler
- » Front-Wheel Drive
- » 2.88 Axle Ratio
- » 80-Amp/Hr 640CCA Maintenance-Free Battery w/Run Down Protection
- » 150 Amp Alternator
- » Gas-Pressurized Shock Absorbers
- » Front And Rear Anti-Roll Bars
- » Electric Power-Assist Speed-Sensing Steering
- » 18.5 Gal. Fuel Tank
- » Single Stainless Steel Exhaust w/Chrome Tailpipe Finisher
- » Strut Front Suspension w/Coil Springs
- » Multi-Link Rear Suspension w/Coil Springs
- » 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs and Brake Assist
- » Wheels: 16 x 6.5J Aluminum Alloy
- » Tires: P205/65R16
- » Tire Mobility Kit
- » Clearcoat Paint
- » Body-Colored Front Bumper
- » Body-Colored Rear Bumper
- » Chrome Side Windows Trim and Black Front Windshield Trim
- » Body-Colored Door Handles
- » Body-Colored Power Heated Side Mirrors w/Convex Spotter and Manual Folding
- » Fixed Rear Window w/Defroster
- » Light Tinted Glass
- » Speed Sensitive Variable Intermittent Wipers
- » Front Windshield -inc: Sun Visor Strip
- » Fully Galvanized Steel Panels
- » Lip Spoiler
- » Metal-Look Grille
- » Trunk Rear Cargo Access
- » Radio w/Seek-Scan, Clock, Speed Compensated Volume Control and Steering

Wheel Controls

» Window Grid And Roof Mount Antenna

- » Bluetooth Wireless Phone Connectivity
- » Passenger Seat
- » 60-40 Folding Bench Front Facing Fold Forward Seatback Rear Seat
- » Manual Tilt/Telescoping Steering Column
- » Front Cupholder
- » Rear Cupholder
- » Valet Function
- » Remote Releases -Inc: Power Cargo Access and Power Fuel
- » Cruise Control w/Steering Wheel Controls
- » Manual Air Conditioning
- » HVAC -inc: Underseat Ducts
- » Illuminated Locking Glove Box
- » Driver Foot Rest
- » Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert and Metal-Look Interior Accents
- » Full Cloth Headliner
- » Cloth Door Trim Insert
- » Urethane Gear Shifter Material
- » Day-Night Rearview Mirror
- » Driver And Passenger Visor Vanity Mirrors
- w/Driver And Passenger Illumination
- » Full Floor Console w/Covered Storage, Mini Overhead Console w/Storage and 3 12V DC Power Outlets
- » Front And Rear Map Lights
- » Fade-To-Off Interior Lighting
- » Full Carpet Floor Covering
- » Carpet Floor Trim and Carpet Trunk Lid/Rear Cargo Door Trim
- » Cargo Features -inc: Tire Mobility Kit
- » Cargo Space Lights
- » FOB Controls -inc: Cargo Access
- » Instrument Panel Covered Bin, Driver /

Passenger And Rear Door Bins

- » Delayed Accessory Power
- » Driver Information Center
- » Redundant Digital Speedometer
- » Outside Temp Gauge
- » Analog Appearance
- » Manual Anti-Whiplash Adjustable Front Head Restraints and Manual Adjustable Rear Head Restraints

Price and Payment Disclaimer - The total sales price is \$12990.00. The displayed **amount financed** is the remainder of the sales price after a \$495 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 213 weekly payments and an interest rate of 9.9% per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

- » Front Center Armrest and Rear Center Armrest
- » Perimeter Alarm
- » 3 12V DC Power Outlets
- » Air Filtration
- » Side Impact Beams
- » Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- » Tire Specific Low Tire Pressure Warning
- » Dual Stage Driver And Passenger Front Airbags
- » Curtain 1st And 2nd Row Airbags
- » Airbag Occupancy Sensor
- » Driver Knee Airbag
- » Rear Child Safety Locks
- » Outboard Front Lap And Shoulder Safety Belts -inc: Rear Center 3 Point, Height Adjusters and Pretensioners

BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

HYUNDAI

SONATA

2015

5NPE24AF1FH002832

VEHICLE MAKE

MODEL

YEAR

VEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:



THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE



FULL WARRANTY.

√

LIMITED WARRANTY. The dealer will pay **100** % of the labor and **100** % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

NON-DEALER WARRANTIES FOR THIS VEHICLE:

warranties under your state's law may give you additional rights.

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
OTHER USED VEHICLE WARRANTY APPLIES.
Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.
SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage,

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- · Heater & Deforester

Brake System

- Failure warning light broken
 Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering SystemToo much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jamsFront wheels aligned improperly (DOT
- Power unit belts cracked or slippingPower unit fluid level improper

Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected

- Spring broken
 Shock absorber mounting loose
 Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- LeakageCatalytic Converters

Airbags

CAR CREDIT NATION DEALER 1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602 **ADDRESS** Chris Maher Jr(540-323-7555) Email: ChrisJr@carcreditnation.com SEE FOR COMPLAINTS I hereby acknowledge notice of the Buyers Guide at the closing of this sale. **CUSTOMERS SIGNATURE** DATE