

Car Credit Nation

WE DELIVER MORE THAN JUST CARS

2016 CHEVROLET MALIBU

Stock #: 20847

Transmission: 6-Speed Automatic

VIN #: 1G1ZB5ST8GF263214

ENGINE: 1.5L/91L

INTERIOR:


DRIVE TRAIN: Front Wheel Drive

COLOR: Summit White

MILEAGE: 84040



Coming Soon



SALES HOURS
Mon-Fri 9am-6pm
Sat- 9am-5pm

Dealer Contact Info
Phone - 540 323-7555
Sales@carcreditnation.com

- » Engine, 1.5L turbo DOHC 4-cylinder DI with Variable Valve Timing (VVT) (160 hp [119.3 kW] @ 5700 rpm, 184 lb-ft torque [248.4 N-m] @ 2500-3000 rpm)
- » Engine control, stop-start system
- » Axle, 3.23 final drive ratio
- » Front wheel drive
- » Suspension, front MacPherson strut
- » Suspension, rear 4-link, independent
- » Brakes, 4-wheel antilock, 4-wheel disc
- » Brake rotors, Duralife
- » Brake lining, high-performance, noise and dust performance
- » Brake, parking, manual
- » Tool kit, road emergency
- » Tires, P205/65R16 all-season, blackwall
- » Tire, compact spare, T125/80R16
- » Wheel, spare, 16" (40.6 cm) steel
- » Headlamp control, automatic on and off
- » Headlamps, halogen
- » Glass, acoustic, laminated, windshield and front side windows
- » Mirrors, outside power-adjustable, manual-folding
- » Audio system feature, 6-speaker system
- » Antenna, Black
- » Seat adjuster, driver 6-way manual
- » Seat adjuster, front passenger 6-way manual
- » Seat, rear 60/40 split-folding
- » Armrest, rear center with cupholders
- » Map pockets, driver and front passenger seatbacks
- » Steering wheel, 3-spoke
- » Steering column, tilt and telescopic
- » Warning indicator, front passenger safety belt
- » Driver Information Center, monochromatic display
- » Windows, power with Express-Down on all
- » Keyless start
- » Compass display
- » Temperature display, outside
- » Air conditioning, single-zone manual
- » Air filter, cabin
- » Defogger, rear-window, electric
- » Power outlet, auxiliary, 12-volt
- » Mirror, inside rearview manual day/night
- » Visors, driver and front passenger vanity mirrors, covered
- » Assist handle, front passenger
- » Lighting, interior overhead courtesy lamp, dual reading lamps and illuminated trunk area
- » StabiliTrak, stability control system with brake assist includes Traction Control
- » Hill Start Assist
- » Daytime Running Lamps
- » Air bags, 10 total, frontal and knee for driver and front passenger, side-impact seat-mounted and roof rail for front and rear outboard seating positions includes Passenger Sensing System (Always use safety belts and child restraints. Children are safer when properly secured in a rear seat in the appropriate child restraint. See the Owner's Manual for more information.)
- » Rear Vision Camera
- » LATCH system (Lower Anchors and Top tethers for Children), for child safety seats
- » Door locks, rear child security
- » Trunk latch, safety, manual release
- » Tire Pressure Monitor System

Price and Payment Disclaimer - The total sales price is \$12990.00. The displayed **amount financed** is the remainder of the sales price after a \$495 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 226 weekly payments and an interest rate of 9.9% per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

CHEVROLET MALIBU

VEHICLE MAKE MODEL

2016

YEAR

1G1ZB5ST8GF263214

VEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:



AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE



DEALER WARRANTY



FULL WARRANTY.



LIMITED WARRANTY. The dealer will pay 100 % of the labor and 100 % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

NON-DEALER WARRANTIES FOR THIS VEHICLE:



MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.



MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.



OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.



SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's law may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

Engine

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

- Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

Brake System

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

Steering System

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

Suspension System

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- Leakage
- Catalytic Converters

Airbags

CAR CREDIT NATION

DEALER

1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602

ADDRESS

Chris Maher Jr(540-323-7555)

Email: ChrisJr@carcreditnation.com

SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

CUSTOMERS SIGNATURE

DATE

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)