
Car Credit Nation WE DELIVER MORE THAN JUST CARS

2013 HYUNDAI SONATA

Stock #:	20871R	Transmission:	6-Speed Automatic
VIN #:	5NPEB4AC3DH682820	ENGINE:	2.4L/144L
INTERIOR:		DRIVE TRAIN:	Front Wheel Drive
COLOR:	BLUE	MILEAGE:	132061



SALES HOURS Mon-Fri 9am-6pm Sat- 9am-5pm

Dealer Contact Info Phone - 540 323-7555 Sales@carcreditnation.com

- » 2.4L DOHC 16-valve I4 GDI engine » Dual continuously variable valve timing
- (DCVVT)
- » 6-speed automatic transmission w/OD,
- SHIFTRONIC
- » Front wheel drive
- » 110-amp alternator
- » MacPherson strut front suspension w/gas
- shocks
- » Independent multi-link rear suspension w/gas » Locking glovebox shocks
- » Front/rear stabilizer bars
- » Engine-speed-sensing pwr steering
- » 4-wheel disc brakes
- » 16" alloy wheels
- » P205/65R16 all-season tires
- » Compact T125/80D16 spare tire
- » Body-color heated pwr mirrors w/timer
- » Body-color grille
- » Chrome window trim
- » Solar control glass
- » Projector-lens headlights
- » Speed-sensitive variable intermittent
- windshield wipers
- » Body-color door handles
- » 104-watt AM/FM stereo w/CD/MP3 player -inc: » Shift interlock system
- (6) speakers, iPod/USB/aux inputs
- » SiriusXM satellite radio w/90-day subscription » Hood buckling creases & safety stops
- » Shark fin style antenna
- » Front bucket seats w/active head restraints » Rear 60/40 split-fold seats w/outboard
- headrests
- » Dual tier console w/armrest, storage, (2) cupholders
- » Rear center armrest w/(2) cupholders » (2) center console mounted 12-volt pwr outlets
- » Full floor carpeting
- » Door sill scuff plates
- » Instrumentation -inc: speedometer,
- tachometer, coolant temp, fuel level,
- odometer, trip odometer, digital clock

» Indicators -inc: PRND, cruise control, turn signal/hazard, high beam, ESC/TCS, ECO

- » Warning chimes -inc: key-in-ignition w/door ajar, seatbelt
- » Trip computer
- » Pwr windows w/driver auto up/down, pinch protection
- » Remote fuel/hood/trunk release
- » Active ECO system
- » Air conditioning -inc: cabin air filter
- » Rear window defroster
- » Cloth door trim
- » Metalgrain interior accents
- » Map pockets
- » (4) door bottle holders
- » Dual sunvisors w/illuminated vanity mirrors
- » (3) assist grips
- » Lighting -inc: dome, front map lights,
- ignition, glovebox, cargo
- » Seatback pockets
- » Rear coat hanger
- » 4-wheel anti-lock brakes (ABS) -inc:
- electronic brake-force distribution (EBD), brake assist
- » Traction control system (TCS) w/electronic
- stability control (ESC)
- » Body-side reinforcements
- » Davtime running lamps
- » Front/rear crumple zones
- » Driver/front passenger seat-mounted side-
- impact airbags
- » Front/rear side-curtain airbags
- » Blue Link telematics system
- » 3-point seatbelts for all seating positions
- » Front seat belt pretensioners & force limiters
- » Childproof rear door locks
- » Emergency internal trunk release
- » Lower anchors & upper tether anchors
- (LATCH)
 - » Energy-absorbing steering column

Price and Payment Disclaimer - The total sales price is \$10990.00. The displayed **amount financed** is the remainder of the sales price after a \$495 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 195 weekly payments and an interest rate of 9.9% per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

HYUNDAI VEHICLE MAKE SONATA MODEL

2013 YEAR

5NPEB4AC3DH682820 VEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:

AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

DEALER WARRANTY

FULL WARRANTY.

LIMITED WARRANTY. The dealer will pay **<u>100</u>** % of the labor and <u>**100**</u> % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST 30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3.000 MILES. WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES. WHICHEVER COMES FIRST 30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

NON-DEALER WARRANTIES FOR THIS VEHICLE:

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.

MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.

OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.

SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, implied warranties under your state's law may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtaina vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

Engine

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by
- faulty transmission or drive shaft • Improper shifting or functioning of any
- gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

Brake System

- Failure warning light broken
 Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering System Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
 Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slippingPower unit fluid level improper

Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected

- Spring broken
 Shock absorber mounting loose
 Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- LeakageCatalytic Converters

Airbags

CAR CREDIT NATION

DEALER

1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602

ADDRESS

Chris Maher Jr(540-323-7555) -----

Email: ChrisJr@carcreditnation.com

SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

CUSTOMERS SIGNATURE

DATE

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)
