Car Credit Nation

WE DELIVER MORE THAN JUST CARS

2012 HONDA Accord

Stock #: 20924

Transmission: 5-Speed Automatic

VIN #: 1HGCP3F83CA014367

ENGINE: 3.5L/212L

INTERIOR:

DRIVE TRAIN: Front Wheel Drive

COLOR: Polished Metal Metallic

MILEAGE: 144640



Coming Soon

Fuel Economy CITY HWY 20.0 30.0

> SALES HOURS Mon-Fri 9am-6pm Sat- 9am-5pm

Dealer Contact Info Phone - 540 323-7555

Sales@carcreditnation.com

- » 3.5L SOHC MPFI 24-valve i-VTEC V6 engine
- » Variable Cylinder Management (VCM)
- » Active Noise Cancellation (ANC)
- » Drive-by-wire throttle
- » Direct ignition system
- » 5-speed automatic transmission
- » Front wheel drive
- » Double wishbone front suspension
- » Independent multi-link rear suspension
- » Front & rear stabilizer bars
- » Variable pwr rack & pinion steering
- » Pwr ventilated front/solid rear disc brakes
- » Chrome dual exhaust finisher
- » P225/50VR17 all-season tires
- » 1-touch pwr moonroof w/tilt, manual sunshade
- » Body-colored bumpers
- » Multi-reflector halogen headlamps w/autoon/off
- » Fog lamps
- » Body-colored heated pwr mirrors
- » Variable intermittent windshield wipers
- » 270-watt premium AM/FM stereo w/6-disc indash CD changer -inc: (6) speakers, subwoofer, MP3/WMA playback, auxiliary input jack, USB interface, radio data system (RDS), speedsensitive volume control (SVC)
- » XM satellite radio w/90-day subscription
- » Integrated rear window antenna
- » Bluetooth HandsFreeLink
- » Leather-trimmed heated front bucket seats -inc: 10-way pwr driver seat, driver pwr lumbar, active head restraints , 4-way pwr front passenger seat, 2-position memory
- » Center console w/sliding armrest, storage compartments
- » Tilt & telescopic steering column
- » Instrumentation -inc: backlit gauges, tachometer, digital odometer, (2) digital trip meters , outside temp
- » Warning lights -inc: door & trunk open, fuel, coolant temp, low oil pressure, low brake fluid, Vehicle Stability Assist (VSA) on, passengerside airbag shut-off
- » Maintenance Minder system

- » Pwr windows w/front auto-up/down, illuminated switches
- » HomeLink garage door opener
- » Security system
- » Dual-zone automatic climate control
- » Rear window defroster
- » Lockable glove box
- » Front & rear cup holders
- » (2) 12V pwr outlets
- » Side door pockets
- » Sunglasses holder
- » Dual illuminated visor vanity mirrors
- » Map lights
- » Dual front seatback pockets
- » 4-wheel anti-lock brake system (ABS) w/electronic brake distribution (EBD)
- » Brake assist
- » Vehicle Stability Assist (VSA) w/traction control
- » Advanced Compatibility Engineering (ACE) body structure
- » Side-impact door beams
- » Daytime running lamps
- » Dual-stage, dual-threshold front airbags
- » Dual-chamber front side airbags w/passengerside occupant position detection system
- » Side curtain airbags, front & rear
- $\ensuremath{\text{\textit{\upomega}}}$ 3-point seat belts in all seating positions -inc: front automatic tensioning system
- » Outboard lower anchors & tethers for children (LATCH)
- » Rear center child seat tether anchor
- » Child-proof rear door locks
- » Emergency trunk release
- » Tire pressure monitoring system

Price and Payment Disclaimer - The total sales price is \$13990.00. The displayed **amount financed** is the remainder of the sales price after a \$995 down payment and does not include taxes, interest, \$495 doc fee, or optional products. The **weekly payment** is estimated with 182 weekly payments and an interest rate of 9.9% per year from the sale date until maturity. Estimated payment shown does not include breakdown protection or GAP products. All customers will not qualify for same interest rate and down payment. Please see dealer for personalized terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

BUYERS GUIDE

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

HONDAAccord20121HGCP3F83CA014367VEHICLE MAKEMODELYEARVEHICLE IDENTIFICATION NUMBER(VIN)

WARRANTIES FOR THIS VEHICLE:

AS IS- NO DEALER	WARRANTY
------------------	-----------------

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

DEALER WARRANTY

FULL WARRANTY.

lacksquare

LIMITED WARRANTY. The dealer will pay **100** % of the labor and **100** % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFER CASE

DRIVESHAFT & AXLES

DURATION:

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES, WHICHEVER COMES FIRST

NON-DEALER WARRANTIES FOR THIS VEHICLE:

warranties under your state's law may give you additional rights.

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.
MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
OTHER USED VEHICLE WARRANTY APPLIES.
Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.
SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, <i>implied</i>

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain avehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safecar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en espanol, pidale una copia de la Guia del Comprador en español

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- · Heater & Deforester

Brake System

- Failure warning light broken
 Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

- Steering SystemToo much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jamsFront wheels aligned improperly (DOT
- Power unit belts cracked or slippingPower unit fluid level improper

Suspension System

- Ball joint seals damagedStructural parts bent or damaged
- Stabilizer bar disconnected

- Spring broken
 Shock absorber mounting loose
 Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- LeakageCatalytic Converters

Airbags

CAR CREDIT NATION DEALER 1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602 **ADDRESS** Chris Maher Jr(540-323-7555) Email: ChrisJr@carcreditnation.com SEE FOR COMPLAINTS I hereby acknowledge notice of the Buyers Guide at the closing of this sale. **CUSTOMERS SIGNATURE** DATE