

Car Credit Nation

WE DELIVER MORE THAN JUST CARS

2013 FORD FOCUS

Stock #: 22883A

Transmission: 6-speed auto-shift manual

VIN #: 1FADP3F21DL217056

ENGINE:

INTERIOR: CHARCOAL BLACK CLOTH SEATS

DRIVE TRAIN: Front-wheel drive

COLOR: GRAY

MILEAGE: 141417



**VEHICLE
HISTORY
REPORT**

Tier 1

Scan for Pricing and
Payment Details



Fuel Economy

CITY HWY
26 36

SALES HOURS

Mon-Fri 9am-6pm

Sat- 9am-5pm

Dealer Contact Info

Phone - 540 323-7555

Sales@carcreditnation.com

- » Front mounted engine
- » Regular unleaded
- » Spark ignition system
- » Transverse mounted engine
- » Aluminum engine block
- » Aluminum cylinder head
- » Alternator
- » Lead acid battery
- » Battery run down protection
- » Radiator
- » Electronic stability control system
- » Front disc and rear drum brakes
- » 4-wheel antilock (ABS) brakes
- » Brake assist system
- » Driver and passenger convex spotter mirrors
- » Reflector headlights
- » Halogen headlights
- » Auto on/off headlight control
- » Multiple enclosed headlights
- » Delay-off headlights
- » ULEV II emissions
- » Tier 2 Bin 4 emissions
- » Capless fuel filler
- » Conventional left rear passenger door
- » Power door mirrors
- » Trunk
- » Heated driver and passenger side door mirrors
- » Conventional right rear passenger door
- » Driver visor mirror
- » Illuminated driver visor mirror
- » Passenger visor mirror
- » Illuminated passenger visor mirror
- » Fully galvanized steel body panels with side impact beams
- » Active grille shutters
- » 4 doors
- » Body-colored front bumper
- » Body-colored rear bumper
- » Grille with chrome bar
- » Black side window trim
- » Body-colored door handles
- » Metallic paint
- » Monotone paint
- » 5
- » Bucket front seats
- » Heated driver and front passenger seats
- » Driver seat with 6-way directional controls
- » Front passenger seat with 4-way directional controls
- » Height and tilt adjustable front seat head restraints
- » Manual front seat head restraint control
- » Fixed rear seats
- » Rear bench seat
- » Fold forward rear seatback
- » Seek scan
- » Single-disc CD player
- » CD player located in the dashboard/instrument panel
- » Radio data system (RDS)
- » CD-R compatible
- » Auxiliary input jack
- » SYNC with MyFord external memory control
- » Standard grade speakers
- » Voice activated audio controls
- » Speed sensitive volume
- » Bluetooth handsfree wireless device connectivity
- » Selective service internet access

Price Disclaimer - The total sales price is **\$5990.0000**. The displayed price is the total sales price not including a **\$495** doc fee, state and local tax, registration fees, interest, or optional products such as GAP insurance or a vehicle service contract. Please see dealer for personalized financing terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Car Credit Nation.

This Page is intentionally left blank

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

Engine

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

- Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

Brake System

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

Steering System

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

Suspension System

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- Leakage
- Catalytic Converters

Airbags

CAR CREDIT NATION

DEALER

1467 FRONT ROYAL PIKE - WINCHESTER, VA 22602

ADDRESS

Jacob Maher(540-323-7555)

Email: Jacob@carcreditnation.com

SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

CUSTOMERS SIGNATURE

DATE

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)